	P. T. T. C.	" man e	
	EGOO'S SPORT & AL	PLIANCE CE	
	ESSAGE	7	EPLY
70	Bloom Inc.	DATE	
BATE	11/11/81	- · · · · · · · · · · · · · · · · · · ·	
	Gustomer claims the rifle went off while operating the bolt on three diff enoughous during benting this past wee	erent	
	The third time was while he was attempt to unload the rifle near his pickup and the rifle discharged sending the bulle three the front-seat of the treat and the three the floor board hitting the frame then back up thru the floor boards.	ting d t	
	Ton may want to send the fifte into Remington since the oustoner is very unhapry about the damage to his compan track, and believes the rifle malfanct Thank you. B. W. Hess owner.	joned.	
1-1-1-0	MEN LIN MENTEN STATE OF THE COPYRET	URN WHITE COPY TO A	CHOCA

Examination of the rifle and trigger assembly could not duplicate the incident that was described. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjustment acrews, indicating no alterations were made on the trigger outside our company. Trigger pull was within our specifications at 34 pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incident. We can only assume that as your customer operated the bolt, he inadvertently brushed, or hit, the trigger which caused the rifle to fire.