

Mr. Dennis:

Please hold this rifle for reply

AHLMAN'S INC.

RT. 1 BOX 20

MORRISTOWN, MINN. 55052

December 14, 1981

Ahlman's Inc.

Route 1, Box 20

Morristown, Minnesota 55052

Gentlemen:

Examination has been
Springfield caliber
to us when it alleged
different occasions.

The returned firearm
examined by our fire
pressure proof test,
indicating that it had
to shipment.

TO: Remington East 300

This firearm has the following defect gas leakage

Refer Customer Letter

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding. Thank you.

AHLMAN'S INC. RT. 1, Box 20, Morristown, MN 55052

The general condition of the gun appeared to be normal. It was noted that there were some slight marks on the stock, and the rear sight and scope screws had been removed. In going over the individual parts, we found the headspace, recoil shoulders, and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the incident that was described. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjustment screws, indicating no alterations were made on the trigger outside our company. Trigger pull was within our specifications at 3 1/2 pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incident. We can only assume that as your customer operated the bolt, he inadvertently brushed, or hit, the trigger which caused the rifle to fire.