

R-86-07765

serious

Allison Carey PT

alleged follow down - Doe

trig + rear worked on
 trig - light + lots of overtravel
 ↳ 2 1/4 lb full-way below
 Rem spec.

.065" rear lift - good + w/in spec.

Overtravel + pendage adjustment
 screws backed out of trig arm

All trig components are correct w/
 no defects. However, the

2 bags + trig overtravel
 specs have been adj out of
 of spec.

Overtravel adjustment is spec.
 pretty well spec.

Not fault

W/ the results to a Rem spec
 a full trig arm w/ your purchase
 (over)