BARBER - Kinzer PPS GAL RE0000269 TIMATE HARMON-OLASS 4033 W. BROADWANY STATE ON THE OWN RAPIDS BLVD. POBB 633-9400 B GENEVA AVE 2001 W/C OAKDALE, MN 738-8195 INTS EXCELSION 781-2665 ROSEVILLE 1ELD 866-4011 Fiver 8225 LYNDALF AVE NS 935-77A1 461.2 OUOTATION TO DATE ADDRESS RESIDENCE PHONE CITY  $-E_{\rm eff}$ **BUSINESS PHONE** ANTITY MATERIALS UNIT PRICE AMOUN Char Impala O tintol 288,05 iller a THIS ESTIMATE IS SUBJECT TO CHANGE AFTER 30 DAYS cam on the safety switch lever lifts the sear Salety the connector and positively blocks the firing pin from moving forward. Therefore, when the safety is "on", there is no way the firing pin can go forward to contact the primer and fire the chambered round. By Model 600 design, it is a mechanical impossibility to fire the rifle with the safety engaged and Our experts also repeatedly tried to fire the rifle upon safety release (off position) without touching the trigger, and no malfunctions of this type were experienced. After numerous attempts to fire the rifle upon safety engagement and upon safety release, the only manner in which your rifle was made to fire was to release the safety and to pull the trigger. Even though your Model 600 is involved in a trigger modification program, the trigger mechanism in your particular firearm is in safe, proper working condition. Only a small percentage of the -1-Sec. Sec.

**BARBER - Kinzer PPS GAL RE0000269**