

## **Service Notice**

6/9/06

To: Remington Authorized Repair Centers

Subject: 700, 7, and 673 Triggers.

Remington has change the 700, 7, and 673 triggers to a new trigger block safety design. The new trigger assemblies are currently being installed on all 700, 7, and 673 bolt action rifles. This is considered a running production change and should not be considered an upgrade under any warranty. The new trigger should only be replaced under warranty when the repair requires trigger replacement as outlined in the service agreement and the bolt lock modification program.

The new style trigger is completely interchangeable with the old style rifles and the new style trigger will be available through the parts department.

Attached you will find diagrams of the changed part for identification.

If we can be of service to you, please feel free to call us at 1-800-310-8483, Monday-Friday, 8am-5pm EST. Please check out our website at <http://www.remington.com>.

Thank you,

Ken Nickerson  
Field Service Support Manager  
Phone 336-548-8783  
Fax: 336-548-7783  
[ken.nickerson@remington.com](mailto:ken.nickerson@remington.com)