

NYLON 76 TRIGGER

Production reported that field complaints were being received from bending of the nylon trigger in warm climate resulting in failures to fire. Research proposed a change to chrome plated delrin to improve the rigidity of the component and give it a metallic appearance. This action met with the approval of the Committee.

Meeting adjourned at 10:45 a.m.

Next regularly scheduled will be held on November 5.

R. A. Morris

R. A. MORRIS
Secretary

RAM:ms