

Sept. 17, 1969

ITEM: 20 GAUGE - DOESN'T TRIP CARRIER LATCH

Cause: The field reports that the magazine spring is too weak.

Corrective Action: None planned. This problem is new to us and will be investigated.

ITEM: FORE-END TUBE BROKEN


Cause: Tabs break off. Cap will not stay tight.


Corrective Action: No current action is planned.

ITEM: CRACKED RECEIVERS AND BARREL EXTENSIONS

Cause: Fatigue.

Corrective Action: A major Research and Production program is under way to improve the life of the Model 1100 barrel extension. Improved barrel life will probably also improve receiver life.


W. E. Leek
R & D


L. Fox
P E & C

LF:WEL:I