

SEPTEMBER 15, 1980

Weaknesses of the M1100 were largely in the rather dangerous area, from a sales viewpoint, of first impression visuals.

Following is a list of the major weaknesses cited on a priority basis.

1. Mismatch of finish on butt stock and fore-end.
2. Link breakage.
3. Lack of rust/corrosion preventative parts in the gas system.
4. Excess and dirty appearing protective lubrication.
5. Fit of wood accessories.
6. Cut-checkering versus pressed.

TWR/kmf