

MODELS 7400 AND FOUR
DEFECTS FROM QUALITY AUDITS

1981

	<u>SEPT.</u>	<u>OCT.</u>	<u>NOV.</u>	<u>DEC.</u>
7400	<p>Rusty Finish on Bbl. Mismatch Disconnecter not adjusted properly. Poor Finish and dent F/E. Poor Finish - F/E. Poor Fit Grip Cap Spacer. Wood Margin Stock to Receiver. Open Grain and Sanding Marks on F/E.</p>	<p>Poor Fit Grip Cap and Spacer on Bbl. Poor Shaping and Light Checkering on F/E. Excess Wood Margin Stock to Rec. Yellow chalk under Finish-Grip Checkering. Miscut R/Sight Base. F/E Miscut. White Spots under Finish of Stock. F/E Cracked.</p>	<p>Excess Wood. Margin, Stock to Receiver. Orange Peel. Oper. Handle broken off. F/E cracked and poor Finish. F/E Tip scratched. Stencil Ink on bottom of Rec. Dent in F/E.</p>	<p>F/E Tip Spacer broken off. Open Grain on F/E. Poor Finish Butt. Plate and Spacer. Safe hits Stock.</p>
FOUR		<p>Sealer on F/E - Dirt along Rails. Oper. Handle tipped-mars Slot. Hammer Marks on Bbl. Green Paint on Stock. Edge of Ejection Port damaged. Poor Polish on Fire Control. Rust on F/E Tip. Poor Finish on F/E. White Spots under Finish of Stock.</p>	<p>Front Sight and Ramp damaged. Elevation Screw missing R/Sight. Min. Header. Poor Polish Bbl. and Bbl. Ext. Edge of Grip Cap polished off. Dull Finish on F/E.</p>	<p>Stems Bottom Bbl. Ext. Poor Wood Repair F/E. Sanding break-through F/E. Poor Fit F/E Cap. Rust on F/E Cap. Bbl. scratched.</p>

Exhibit 8