

information. The Committee decided that a statement of the extent of the recall advertising should be included in future minutes.

SAAMI - NSSF Safety Advertising

Copies of the four revised NSSF safety warnings were reviewed. The revisions reflect Remington's request that the four following areas be incorporated in the booklet and poster:

- obtain and read the Owner's Manual
- use proper cartridge or shell in the gun chambered for it
- periodic maintenance check of firearms
- never alter or modify a firearm

NSSF decided to incorporate them in the existing ten rather than adding four new items. A copy of the revised wording for the NSSF booklet and poster is attached as Exhibit "C".

870 Competition Trap Gun

Firearms Research reported that a crack occurs occasionally at the rear of the ejection port. Tests were conducted to determine if this could develop into a safety hazard. Five guns were tested with one extremely high pressure round each to evaluate the severity of the resulting failures. The guns tested as follows:

- 2 new unaltered guns
- 2 guns cut through rear of port
- 1 gun cut half way through front of port

All guns failed in a manner typical of that caused by an