

11/2/89

To

Findings reported
From ROGER POTTER
to customer; keep
Couldn't duplicate incident



However:

Bolt Stop Pin

+
Trig Pin

have been
removed +
put in
backwards

↓
PLUS
↓

Stop Screw

+
Trig adj. screw

have been
removed -
factory seals
broken

↳ Trig adj. screw
protruding 1/4" from housing

Needs new trig assey -
25.00 COD charge (approx)