

R-16-01 107

~~CONFIDENTIAL~~

serious

allison curry PT

alleged follow down - Dos

frig + rear worked on
 + frig - light + lots of overtravel
 ↳ 2 1/4 lb pull - way below
 Rev spec.

.065" rear lift - good + w/inspec.

Overtravel + pendage adjustment
 screw backed out of frig main

all frig components are correct w/
 no defects. However, the
 base + frig overtravel
 specs have been adj. out of
 spec.

Overtravel adjustment of spec.

Revised spec.

Not found

in the past for the same

work. The work was done at the same time.