

MOD. 700
 Ser. No. 6250346
 Date. 1-6-83
 Inspected By R. C. McLean
 Insured _____

R# 01226
 P# 16
 MFD. 7-69

COMMENTS:

7-12-83

- (9) THE CONNECTOR DID NOT APPEAR TO BE TIGHT TO THE TRIGGER.
- (10) THERE APPEARED TO BE A RELATIVELY LARGE AMOUNT OF PLAY BETWEEN TRIGGER AND CONNECTOR.
- (11) THERE WAS FINE SANDY GRIT THROUGHOUT THE HOUSING.
- (12) THERE WERE NO RUFFS AROUND THE TRIGGER HOLE IN THE INSIDE OF THE HOUSING PLATES.
- (13) THE TRIGGER SPRING WAS SHARP AT BOTH ENDS.
- (14) RUST WAS ON BOTH SIDES OF THE TRIGGER.
- (15) THE SIDE OF THE CONNECTOR WAS SLIGHTLY BULGED ADJACENT TO THE HOLE AND THERE WAS A BURN MARK ON THE BULGE.
- (16) THERE WAS A BUMP ON THE TRIGGER BOTTOM WHERE THE CONNECTOR PIVOTS.
- (17) THE SURFACE ON THE BACK OF THE SEAR WAS NOT AS SMOOTH AS SEARS OBSERVED IN THE PAST.