

OPERATIONS COMMITTEEFIREARMS - TRAPSMINUTE #6 - 1975

P. H. BURDETT
J. P. McANDREWS
E. SPARRE - E. HOOTON, JR.
H. M. STOESSEL
J. G. WILLIAMS
R. A. PARTNOY
E. F. BARRETT
E. B. BEATTIE
L. FOX
L. J. SCOTT

F. E. MORGAN
R. C. MAY
R. L. HALL
J. H. HODGSON
A. J. HERMANDORFER
W. E. LEEK
D. S. FOOTE
T. J. SHARPE
J. H. SWEENEY

COPY NO. BookOPERATIONS COMMITTEE
ILION DIVISION

MARCH 21, 1975

PRESENT:

Committee

J. P. McANDREWS, CHAIRMAN
E. SPARRE
E. F. BARRETT
J. G. WILLIAMS
E. B. BEATTIE
L. FOX
J. H. SWEENEY, SECRETARY

Others

E. HOOTON, JR.
H. D. ALBAUGH
F. T. MILLENER
R. W. STEELE
L. J. SCOTT
R. B. SPERLING ✓
R. L. HALL
C. B. WORKMAN
W. E. LEEK
J. P. LINDE
J. S. MARTIN

The meeting convened at 9 a.m. at Ilion.

NOT FOR REPRODUCTION
OR FURTHER DISTRIBUTION

[REM 0027643]

C
H
A
P
A

Product deficiencies known or suspected in 1975 - Exhibit 15.

[REM 0028349]

[REM 0027644]

BUSINESS MEETING - contd.RESEARCH PERFORMANCE

In response to product deficiencies reported by Marketing, R & D made the following reply:

- . Model 700 three position Safety - development of this feature is in progress.
- . Model 788 Bolt Handle failures - a revised design for Bolt Handle attachment is in test.

The R & D report on progress versus schedule follows:

Program

Release Design
Schedule

[REM 0028221]

[REM 0027645]

REMINGTON PRODUCT DEFICIENCIES KNOWN OR SUSPECTED

C
H
A
P
A

REM 0028350
REM 0027864

EXHIBIT

E. M/700 SAFETY

- EASE OF OPERATION AND SAFE GUN HANDLING DEMAND A DESIGN THAT ENABLES THE SHOOTER TO OPERATE THE ACTION WITH THE SAFETY "ON".

[REM 0028223]

[REM 0027665]

PRODUCT DEFICIENCIES (KNOWN OR SUSPECTED) 1975

Remington 3200 -

Model 1100 -

Model 1100 and 870

Model 742 -

Model 700 - three position safety would be desirable.

Model 788 - bolt handle breakage.

[REM 0026214]

[REM 0027621]