

make or the trigger outside our company. Trigger pull was within our specifications at 4 pounds. It was seen left with safety in the "on safe" position at .512"

The Model 110 test was so designed to have a "lag-¹²³lag" configuration on the left handle to position the operators hand downward and away from the trigger when closing the bolt. The modification made to the right, with the Model 700 test handle, places the hand directly in line with the trigger on bolt closing. We consider this to be an unsafe condition and the probable cause of the incident you described.

Based on our findings, the Dominion Arms Company cannot accept any liability or responsibility for the unfortunate incident. We can only assume that accidental contact was made with the trigger on closing the bolt, as the owner of the rifle is sure. Therefore, we are returning the rifle to you as we received it.

Thank you for allowing us the opportunity to examine the rifle and report our findings.

Sincerely,

J. E. Barber