

CUSTOMER ORDER NO.		COMMENTS					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
22/88	11/30/88	EM 10-65	A6833899	700 30-06 BDL		R 88-31736	
SERIES	W/STUDS		W/SWIVELS				

SHIP TO:	
A. DEINTINIS 370 CHAMBERLAIN AVE. PATERSON, N.J. 07502	A. DEINTINIS 370 CHAMBERLAIN AVE. PATERSON, N.J. 07502

INT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				12/5/88	UPS

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

MER'S REQUEST

on several occasions the firing pin did not fall when the trigger was pulled.

trigger assembly full of solidified, sticky lubricant - bolt is sticking so is safety cam. Could not replicate complaint, but entirely possible it happened as stated in cold temperatures

1) Replace trigger assembly with new assembly with bolt lock, at no charge.

2) expedite repair and return of rifle to sender.

12/20/88
Jas.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JJB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88