

R 92-08537 ^{ORDER}

CUST NO:000444 ILION L

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"... the rifle discharged when the safety was put off"					F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT No fault found - trigger and safety assembly operate normally on every repeat. Cannot hydrate compound

Trigger pull 5½ pounds; acc-lift .0075" H

PARTS	COMMENTS	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	Offer to return rifle as-is, or to replace trigger assembly at normal cost as a gesture of good- will, if that will better show confidence in the rifle.	RJR					
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. B/91

PPS 01789