


cc: E.P. Barrett

		<b>DATE</b> 12/20/81 <b>FILE NO.</b> <b>ATTENTION</b> <b>SUBJECT</b> Rem 700 - DL - 6225526 - 308CA	
17210 17210		<input type="checkbox"/> URGENT <input type="checkbox"/> CLAIM AS POSSIBLE <input type="checkbox"/> NO REPLY NEEDED	

 RT, BIA  
 Remington-Union  
 Rem. 17210

gun fires when the bolt is closed.  
 Witness repair and return.

SIGNED

*Charles E. [Signature]*

DATE OF REPLY

SIGNED

RECIPIENT: WRITE REPLY, RETURN WHITE TO SENDER. KEEP THIS PINK COPY.

Further examination revealed that the trigger assembly was full of solidified oil, to the extent the bolt stop lever was barely operable.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the reported malfunction. We can only assume that the oil accumulation, under certain circumstances, caused the accidental discharges. As stated in the Owner's Manual, the Model 700 trigger assembly is designed not to require any lubrication, and care should be taken to avoid oil getting into the mechanism.