

**Remington**



REMINGTON SERVICE  
R-89-05490  
Fit new trigger assm. with bolt  
lock, & check bolt cam  
Bill Ericson  
Jim Hutton

**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 8, 1989

Mr. Charles E. Hunter  
R.D. 1, Box 64  
Morris, PA 16938

Dear Mr. Hunter:

Our experts have completed their examination of your Model 700 BDL 243 caliber rifle, serial number 118823, that you returned with the problems that the trigger is bad, and it will not cock.

The returned firearm, which was produced in October of 1964, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general condition of the rifle appeared to be good, but well used.

Removal of the barrel-action from the stock assembly revealed that the trigger assembly was extremely wet with excessive oil. In future use, we strongly advise that oil be used sparingly and not let accumulate in or on the trigger assembly, as this condition could adversely affect the operation of the trigger assembly.