

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS W/LEUPOLD 3X9 SCOPE	
DATE RECEIVED 4/22/91		DATE OPENED 04/24/91		DATE CODE PR 6-68	
ACCESSORIES W/STUDS		HARD CASE		SCOPE MNTS	
L		J		L	
COUNT NUMBER		ACCOUNT NUMBER N/C		WRITE ☐ CLEAN/TEST	
PROM. DATE		ESTIMATED		VIA ☒ UPS	
PAIR CHARGE TAX INSURANCE UPS PARCEL POST TOTAL UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☐ MARRED CUSTOMER'S REQUEST: "...at times fire sometimes, and other it fails to fire. After I pull the trigger, it will fire on a delayed period of time." MAIN FAULT: Trigger assembly is contaminated with an oily, gummy residue. As received, the rear sight cam is sticking to the trigger assembly side plate. Rifle operates normally at room temperature, however, cold temperatures could cause the described problems. RTS: Clean present trigger assembly, if possible, if not, send repair quotes for a replacement trigger assembly at $\pm$ normal cost, as a gesture of good-will.					
REPAIRMAN		PROOF		CLEAN	
GALLERY TESTER		DATE		DATE	
TEST		D. TE		DATE	
TARGET		PATTERN		DATE	

OFFICE COPY

RD6925 REV. 7/90