

Dennis.

15/50

T.P. 4 3/4" / S.L. 0125

SEAR Engagement Appears Under
FACTORY Spec - TR15 HAS DAMAGE
ON LEFT SIDE MAYBE BINDING
IN TR19 GUARD REPLACE TR19
ASSY. Gummy Residue Is EVIDENT
THROUGH OUT

Martin