

RECEIVING AND ESTIMATING REPORT

INITIAL FPS		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 11/26/90	DATE OPENED 11/28/90	DATE CODE A0 3-77	SERIAL NUMBER A6438672	MODEL AND GRADE 700 264 WIN	BDL/MAG	ORDER 90-308	
ACCESSORIES SCOPE BASE L/STUDS							

FROM:

MEDENWOLD, KM
RR 1
HANKINSON ND 58041

SHIP TO:

MEDENWOLD, KM
RR 1
HANKINSON ND
58041

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 12-17-90	VIA V45672957
----------------	--------------------	--------------------------------	------------	------------	-----------------------	------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Safety needs to be changed. Goes off when opening Bolt. Check B3L see if it will group.

MAIN FAULT

Cannot duplicate complaint - Trigger assembly and safety function properly. However, the trigger assembly has been improperly adjusted outside of factory (excessive overtravel) and the internal pull and overtravel screws have had the adjust removed and not replaced.

PARTS

- 1) Gallery test up for accuracy
- 2) Offer to either properly re-adjust the present trigger assembly or offer to replace trigger assembly at \$ normal price as a gesture of good-will, if it will better restore confidence in the upl.

REPAIRMAN R3L	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/8