use, we strongly recommend that oil be used sparingly and not let accumulate in or on the trigger assembly, and that the trigger assembly not be adjusted by untrained non-Remington personnel, as both of these conditions could adversely affect the operation of the trigger assembly.

As a gesture of good-will, we are replacing the complete trigger assembly with our current style at no-charge. This was requested by your customer and noted in your message/reply form.

Thank you for having afforded us the opportunity to be of service, and we trust that our handling meets with your approval.

Sincerely,

Product Service

DJS:tpp

Remington Arms Company. Inc.