

PAGE (4) of (4)

uuu-82

MOO. 760R# 51224SER. NO. 6259346P.I. 1/6REC'D. 1-6-83MFD. 7-69CHECKED BY R. McLeanNUMBER

COMMENTS:

7-12-83

(9) THE CONNECTOR DID NOT APPEAR TO LAY TIGHT TO THE TRIGGER.

(10) THERE APPEARED TO BE A RELATIVELY LARGE AMOUNT OF PLAY BETWEEN TRIGGER AND CONNECTOR.

(11) THERE WAS FINE SANDY GRIT THROUGHOUT THE HOUSING.

(12) THERE WERE NO BURRS AROUND THE TRIGGER HOLE IN THE INSIDE OF THE HOUSING PLATES.

(13) THE TRIGGER SPRING WAS SHARP AT BOTH ENDS.

(14) RUST WAS ON BOTH SIDES OF THE TRIGGER.

(15) THE SIDE OF THE CONNECTOR WAS SLIGHTLY BULGED ADJACENT TO THE HOLE AND THERE WAS A BRIGHT MARK ON THE BULGE.

(16) THERE WAS A BUMP ON THE TRIGGER BOTTOM WHERE THE CONNECTOR PIVOTS.

(17) THE SURFACE ON THE BACK OF THE SEAR WAS NOT AS SMOOTH AS SEARS OBSERVED IN THE PAST.