

RECEIVING AND ESTIMATING REPORT

R 92-21775

ATTN: JIM STEKL

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
10/13/92	10/19/92	PQ-6-78	A6626021		700 30-06 BDL
ACCESSORIES	W/STUDS				

FROM:

SHIP TO:

NC 28659

NC
28659

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

Category	Value
1	100
2	200
3	300
4	400
5	500
6	600
7	700
8	800
9	900
10	1000
TOTAL	5400

CYCLE	A1	B1				
TRIGGER GROUP	1)	B2	has fired on two occasions	E1	F1	while performing safety
BOLT ASSY.		B3	from "safe" position to "fire" position	E2	F2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.	2)	B5	stroke "just cracked" - no "mouse" -	E4	F4	behind bolt handle mount
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

- 1) cannot duplicate complaint - info and safety ops not properly in every respect. Tugger pull 3 1/2 pounds; wear left .008"
- 2) this is old grade - post wood warranty - info produced 6/78
the crack does not weaken stock at all.

[illegible]

REV. 1/5

PPS 03812