

RECEIVING AND ESTIMATING REPORT

INITIALS PS		CUSTOMER ORDER NO.		COMMENTS	
DATE RECEIVED 2/28/91	DATE OPENED 03/06/91	DATE CODE DR 9-68	SERIAL NUMBER 370141	MODEL AND GRADE 700 30-06	ORDER R 91-0645
ACCESSORIES L/BARREL					

L/REAR SIGHT

FROM:	SHIP TO:
SHAW, JEFF 2389 DUNE DR C/O SHAW BROS ROOFING CO AVALON NJ 08202	SHAW, JEFF 2389 DUNE DR C/O SHAW BROS ROOFING CO AVALON NJ 08202

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED 3-14	VIA UPS
--------------	--------------------	---	------------	-------------------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *Trig + safety may be defective, fired once when safety was released, sometimes fired 2 or 3 seconds after trig is pulled.*

IN FAULT *Cannot duplicate complaint, however, trigger assembly and firing pin assembly are contaminated with excessive oil and dirt. This in combination with cold temperature could explain the delayed firing.*

RTS	<i>Clean firing pin and trigger assembly, if possible. Or, we can install a new trigger assembly at $\pm$ normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.</i>					
	REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90