

Remington

DATE 5/25/88 15

WAIT REPLY & CHECK

Remington

REMINGTON ARMS COMPANY, INC. OR R.O.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS


PLEASE MAIL
REMITTANCE
TO BOX CHECKED

BRIDGEPORT, CONN. 06602

X UNION, N. Y. 13357

INVOICE NO R-88-12950

INVOICE DATE

SOLD
TOVictor E. Spear
R.R. #2
Box 61
Churubusco IN 46723

OUR ORDER NO R-88-12950-700

OUR ORDER NO

SHIP: VIA UPS

Ad 3-72

700 243 6539015

L/wood, scope base, L/sight on rear ramp

COMPLAINT: Almost every time bolt is let down it fires-also
fires when safety is released.MAIN FAULT: Trigger has been grossly misadjusted outside
factory. Trigger pull 1 pound, rear engagement so misadjusted,
rifle will not cock most of the time.

1. 26345 Trigger assem. R.O.C.
2. Polished chamber
3. Check heading

TOTAL REPAIR CHARGE	35.00
TAX 55	1.75
PARCEL POST UPS	3.44
TOTAL CHARGES	40.19

40.19

THE ITEM ABOVE HAS BEEN RECEIVED AND IS BEING RETURNED TO THE
CUSTOMER. IF THE CUSTOMER DOES NOT RECEIVE THE ITEM, THEY SHOULD
CONTACT THE SELLER IMMEDIATELY. THE SELLER WILL BE RESPONSIBLE FOR
THE RETURN OF THE ITEM TO THE CUSTOMER.

THE CUSTOMER MUST SIGN AND RETURN THIS COPY TO THE SELLER WITHIN
4-6 weeks. CUSTOMERS SIGNATURE