

ORDER
R92-19772

ATTN: JIM STEKL

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
09/18/92	09/30/92	DM 9-65	172039		700 30-06 ADL
ACCESSORIES	W/STUDS	SCOPE BASE			

SHIP TO:

WALKER, K C
3010 VILLAGE LANE
DEER PARK

TX 77536

WALKER, K C
3010 VILLAGE LANE
DEER PARK

TX
77536

CUST NO: 067305 C.O.D L

WRITE ☐ CLEAN/TEST

VIA

R638163:

☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL 100.00 100.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
------------------	------	----------	--------	----------	-----	---------

CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

MAIN FAULT Trigger assembly is contaminated with sticky, gummy substance (probably WD-40) to the point that the sear & safety cam are sticking to the side walls of the trigger guard body. Rifle not operating properly as a result of some delay firing pin follows down on bolt closure. This condition is causing a delay in firing pin full when trigger is pulled. Rifle has not been properly maintained.

'ARTS

COMMENTS

COMMENTS: After replacement trigger, received at 4 month cost, as gesture of good will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE _____

DATE

DATE _____

DATE _____

DATE _____