#### **BARBER - Kinzer PPS GAL RE0008775**

Remington Arms Co., Inc. Product Service Legal Case #:2519

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

147004 7/3/2008 7/7/2008 7/7/2008

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Hilltop Gun Shop Hilltop 1439 Junction Rd Falls of Rough KY 40119 W 270-769-7605
E rusty.mcgee@remington.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4006 Altered Adjustments or Components

Concern: 1007 Fired on Safe Release

Unknown

S C

7/8/09 owner states that the firearm has discharged upon dissengaging the safety 4 times. cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 RF/A
 700/243 WIN
 20000
 A6309626
 PI
 6/3/1976

Remington RF/A 700/243 WIN 20000 A6309626

Date Purchased Where Purchased Accessories Original Owner

SS KRESGE LAWRENCE KS TWO PIECE SCOPE BASE U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/RF/A

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV Cash Date APV APV

quoted for

repair

Repair/Replacement Repair/Replacement

Cost Date

7/8/2008


7/8/08 dealer has approved the charges on the repair. cm

Examination[Remington/RF/A]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date	Ī	7/7/2008
Examination	Product Type		RF
	Action Type	]	A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
	Description		22" 243 WIN
	Date Code	]	PI
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
			7

## BARBER - Kinzer PPS GAL RE0008776

1	Firing Pin	Slightly Worn; Functioning	1
	Shroud	Slightly Worn; Functioning	<del></del>
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Managina	Condition	Select	
Magazine	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Missing	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
<u></u>	Sub-Assembly	Non-ISS	
Tests	Test Fired	False	
Tests	Feeding Test	False	
	Condition	Slightly Worn; Functioning	DIRTY/STICKY
  Trigger	Pull	Select	2.5#
1118801	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE





### General Repair Form

Back to Repair Services

NOTE. Please complete and print this form, and then include it with your firearm

Model Number: 700	Serial Number: A	6309626	
Name: Hilltop Gun Shop	Date of Purchase:	Date of Purchase:	
Address (no PO Boxes): 1439 Junction Roa	d		
City: Falls of Rough	State: KY	Zip: 40119	
Phone (Daytime): 270-769-7605	Fax:		
E-mail Address: rusty.mcgee@remington.com	n		

Please describe your problem:

I am shipping this firearm for a customer. He states that the firearm has discharged upon dissengaging the safety four times.

Thank you Rusty McGee

347

A6309626

Model: characters left

NOTE: Prior to shipping your firearm, contact the Repair Center f

(1) WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOU FIREARM THIS IS A VIOLATION OF FEDERAL LAW. IF YOU THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADD SERIAL NUMBER OF YOUR FIREARM

700 RE00147004

Record the serial number of your firearm before sending it.

Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)

Remove all accessories from your firearm to prevent loss or damage.

Ship your ENSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier

©2008 Remington Arms Company, Inc. All Rights Reserved. Investor Relations | Other Remington Brand Products | Legal Notices | About Us Visit Our Other Websites

Other Sites

Remington

TRIG. SETSCIEWS ALTERED. will Rollow down. Ting. Reminigion Arms Co., INC. White BOLT LOUR PROGRAM

Attn: Arms Service Division

Let Han 11-1

14 Hoefler Avenue Flien, NY 13357

http://www.remington.com/support/repair services/general repair form.asp

6/20/2008

Remington Arms Co., Inc. **Product Service** Legal Case #:3120

Case Information

RE# **Date Opened** 157920

Date Opened(PS) 1/23/2009 1/22/2009

**Date Closed** 1/23/2009

**Incident Date** 

Pre Lit Lit Obsolete

Customer Information

Type Business First Name Last Name

Street

State Zip Age City

Contact

Incident

Ronald Hoffbauer 4059 E. Cholla St. Phoenix AZ 85028

W 602-277-3776 ext 205 E rlhoffbauer@cox.net

Incident Information

Claims

Codes

Repair Est.

Medical **Treatment**  Medical Status

ΡI

PD

Cause: 4038

Could Not Duplicate

Concern

Gun discharged when moved from Safe to Fire

Concern: 1007 Fired on Safe Release

While hunting in Nov 2008, I moved the safety from Safe to Fire to unload the rifle and it discharged. dmf

Unknown

C

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

OR

357981

DOM 7/1/1968

Reminaton **Date Purchased** 

CF/BA Where Purchased 700/3006 SPR **Accessories** 

**Original Owner** 

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

**Release Date** 

Reimbursement

Cash Settlement Reim. Cash **Date Date** 

**APV** 

APV

Repair at special price under BLSM program

> Repair/Replacement Repair/Replacement **Date**

Cost

1/26/2009


\$79.88 1/26/09: Customer was mailed an estimate for \$35. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/23/2009
Examination	Product Type		RF
ł	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		22" 3006 SPR
	Date Code		OR

lı.	1	<b>_</b>	
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
<i>,</i>	Handle	Slightly Worn; Functioning	]
	Stop	Slightly Worn; Functioning	]
	Condition	Slightly Worn; Functioning	]
Extractor	Cut Condition	Slightly Worn; Functioning	]
	Ext/Eject Test	False	
	Block Condition	Select	]
Locking	Lug Condition	Slightly Worn; Functioning	]
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	*Modified	]
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
Trigger	Pull	Select	6#
i i igger	Altered	True	SAFETY SWITCH ALTERED
	Sub-Assembly	M/700 Bolt Lock	

#### **BARBER - Kinzer PPS GAL RE0008781**



RONALD L. HOFFBAUER

4059 E. CHOLLA STREET – PHOENIX, ARIZONA 85028 TELEPHONE (602) 996-0596

December 12, 2008

3120

27/68 22" 600

Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357

RE: Remington 700 30.06 SN 357981

Dear Sirs:

I am sending my rifle for replacement of the safety. During my deer hunt in November 2008, at the completion of a hunting day without any having an opportunity at a shot, I moved the safety from Safe to Fire in order to unload the rifle. When I pushed the safety to fire, the gun discharged. I had previously used the gun for elk hunting about two weeks prior without any problems. It is my understanding that the cost for the replacement under the recall listed on your web site is \$20.00. To my knowledge, no prior work has been done on the gun. I purchased it used from a dealer.

It is my understanding that you may send the gun to a dealer to effect the repairs. If that is the case, I would like to get an estimate for adjusting the trigger to a 3 to 3 ½ pound pull, if that is possible. I would also like to get an estimate for replacement of the recoil pad to a limbsaver pad or a pad similar to that installed on the Remington 700 XCR in 375 that I recently purchased. Please call me at (602) 277-3776 x 205 which is my place of employment or email me at rlhoffbauer@cox.net.

If there is any questions, I can be reached at the above address, phone number or email address.

Very truly yours,

Ronald L. Hoffbauer

could not duplicate concern. SALETY SWITCH Altered + WILL JAN OFF. Suphre TPA, checkonege let N WHERE BOIT LOCK MOGRAM ROR X 20,00 + STH

Quote

357981 Model: 700 MILLIAN DE PEQUI 157920

Remi	ngton.
Factory Repair (NOTE: Please print and complete this for	ir Instructions rm, and then include It with your firearm.)
Model Number: 700 ADL 30.06	Serial Number: 357981
Are you the original owner?:	
Name: Ronald L. Hoffbauer	Date of Purchase:
Address (no PO Boxes):	
4059 E. Cholla Stre	et
City: Phyenex	State: AZ Zip: 85028
Phone (Daytime): 602 - 277- 3776 x 205	Fax:
E-mail Address: r/hoffbauer @	cox. net.
Please describe your problem: recall no	pair on safety. when
safety moved from Safe y	6" Fire to unload, The gun
discharged.	
	- H - H - H - H
	ment of the second seco
Ammunition Information:	
Manufacturer:	Туре:-
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used:	Powder Weight:

# City: Phone (Daytime): 60 E-mail Address: I would like to rece Please describe your | **Ammunition Informat** Manufacturer: Other (i.e. bullet weight/ **Handload Information** Powder Used: Primer Used: Case/Hull Used: Bullet Type/Shot Size: Reloader Used: Firearms Care (Cleaning and Lubrication): Bright Brand of cleaning solution used: How often do you clean the bore? (Months or Number of rounds) Affer even How often do you clean the action? (Months or Number of rounds) How often do you clean the trigger assembly? (Months or Number of rounds) after extende once Brand of lubricant used:

ATTN: Arms Service D 14 Hoefler Ave Ilion, NY 13357		
REMINGTON ARMS CO	., INC	
p your INSURED firearm by either UPS or Parcel Post to:		
at were the services performed?		
en was the last time that your firearm was serviced by a Remington	authorized repairman/gunsmith	unkn
nments:		
ye you reviewed the cleaning and maintenance recommendations or YES NO	our web site or in our owners m	nanuai?
w often do you lubricate the trigger assembly? (Months or Number o	of rounds)	
w often do you lubricate the action? (Months or Number of rounds)	See above	

SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.