

BARBER - Kinzer PPS GAL RE0009054

Remington Arms Co., Inc.
Product Service
Legal Case #:2403

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 145423 | 5/12/2008 | 5/13/2008 | 5/14/2008 | | | | |

Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|----------|------------|-----------|---------------------------|-------|-------|-------|-----|--|
| Reporter | | Keith | Pasternak | 143 Riverside Drive North | Brick | NJ | 08724 | | H 732-539-1867 E grizbear@comcast.net |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|-----------------------|----------------------|-----------------------|----------------|
| PI | | | | |
| PD | Cause:4015 | Improper Maintenance | Unknown | |
| S | fires on safe release | Concern:1007 | Fired on Safe Release | |
| C | | | | |

5/14/08-correspondence from repair-firing pin is releasing when safety is pushed forward. Sometimes pin drops when bolt is closed.lw

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl | DOM |
|----------------|-----------------|--------------|----------------|--------|-----|----------|
| Remington | CF/BA | 700/3006 SPR | | 77489 | KP | 5/1/1967 |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | | | U | | | |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

| Settlement | Release of Claims | Release Date | Reimbursement | Cash | Reim. Date | Cash Date |
|----------------------|-------------------------|-------------------------|---------------|------------|------------|-----------|
| | | | | Settlement | APV | APV |
| Replace TA under smp | | | | | | |
| | Repair/Replacement Cost | Repair/Replacement Date | | | | |

5/14/08-quote sent to replace TA under smp.lw

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|------------------------|----------------------|--|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 5/13/2008 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | F.SUPRY |
| Cause | 4015 | Improper Maintenance | TRIGGER ASSM DIRTY,STICKY. PARTS WORK SLUGGISH |
| Barrel | Description | | 20" 3006 SPR |
| | Date Code | | KP |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2403&Type=Case>

5/15/2008

| | | | |
|--------------|------------------------|--------------------------------|---------------------------------|
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| Bolt | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| | Face | Slightly Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| Extractor | Condition | Worn; Functioning | |
| | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | ---Select--- | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | ---Select--- | |
| Overall | Exterior Condition | Worn; Functioning | |
| | Stock Condition | Worn; Functioning | |
| | Fore End Condition | ---Select--- | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | |
| Safety | Description | | STANDARD M/700 BOLT LOCK SAFETY |
| | Function | Slightly Worn; Functioning | |
| Sear | Lift | ---Select--- | .016 |
| | Notch | Slightly Worn; Functioning | O/S TWO PIECE |
| | Tests | Test Fired | False |
| Feeding Test | Tests | False | |
| Trigger | Condition | Slightly Worn; Not Functioning | WILL FOLLOW DOWN DIRTY,STICKY |
| | Pull | ---Select--- | 4.5# |
| | Altered | False | |
| | Sub-Assembly | M/700 Bolt Lock | |

2403



General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

KP S/b7
20"
4.5#
.016

| | | | |
|---|-----------|----------------------|--|
| Model Number: 700 | | Serial Number: 77489 | |
| Name: Keith M Pasternak | | Date of Purchase: | |
| Address (no PO Boxes): 143 Riverside Drive North | | | |
| City: BRICK | State: NJ | Zip: 08724 | |
| Phone (Daytime): 732-539-1867 | | Fax: 732-840-1142 | |
| E-mail Address: grizbear@comcast.net | | | |
| Please describe your problem: | | | |
| <p>Firing pin is releasing when safety is pushed forward, or sometimes the pin drops when the bolt is closed.</p> <p>How I found out? While I was at the range, this happened and the firearm discharged. As always the muzzle was pointed in a safe direction. It is unsafe to use this weapon and it is dangerous. I would like to take place in the safety modification program and as the representative informed me the firearm will be fully inspected, cleaned and repaired to be a safe functioning firearm.</p> | | | |
| 1 characters left | | | |
| NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time. | | | |
| <p>Ⓢ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your ENSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p> | | | |

Number: 77489

Model: 700



RE00145423

Trig. Assm. very dirty + sticky. will follow down. replace TPA, check over, clean, function test under bolt lock program for \$20.00 + s&h.

Quote