

BARBER - Kinzer PPS GAL RE 0009861

Remington Arms Co., Inc.

Product Service

Legal Case #:4624

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
197686	6/22/2010	6/25/2010	6/25/2010				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Beikirch Ammunition Corp		Beikirch Ammuni	PO Box 151 930 Linden Ave	East Rochester	NY	14445		W 585-248-3660
Incident		Carl	Bestor						H 377-1858 C 645-3216

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fired when bolt closed twice	Concern:1008 Fired on Bolt Closing	Unknown	
C				

6/30/10 Per note with rifle, the customer purchased it used from someone and it seems like some trigger adjustments were attempted and twice the rifle has gone off when the bolt was closed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	A6411404	BO	1/26/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	C F WOLFERTZ ALLENTOWN PA	SEE THRU SCOPE RINGS	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA at BLSM program price, \$20 + S&H						
Repair/Replacement Cost	Repair/Replacement Date					

6/30/10 Per Ilion, could not duplicate concern. Replace TPA under bolt lock program for \$20, check over and clean.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/25/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		BO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.007
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SEE THRU SCOPE RINGS

BARBER - KILZER PPS GAL RE 00098853

The image shows the front cover of a book. The cover is a dark, almost black color with a prominent woven fabric texture, possibly buckram or a similar heavy textile. There are subtle variations in tone and some minor wear or creases visible across the surface, particularly along the edges. The lighting is even, highlighting the fine details of the fabric weave.

801/77

22"

4#

1007

BEIKIRCH**AMMUNITION CORPORATION**

P.O. Box 151 • 930 LINDEN AVE. • EAST ROCHESTER, N.Y. 14445-0151

PHONES (585) 248-3660 248-3434 FAX (585) 248-3973 (800) 622-3006 ORDERS ONLY!

Invoice Date

6-18-10

Customer #

TO

Remington Arms Co.

Arms Service Dept.

Action New York 13357.

Order Date

TERMS: NET 20 DAYS FROM D.O.I.

1 1/2% PER MONTH AFTER 20 DAYS

INVOICE

PHONE

AMOUNT

Serial A6411404

Att Service:

Enclosed please find
 this model 700 BDL 30-06 for the
 following reason - Customer purchased
 it used from someone and it seem
 like some trigger adjustment were
 attempted and twice the fire has
 gone off when the bolt was closed.
 Please checkover and repair as
 necessary to make it safe. Thank you

Sincerely,

Carl Besta.

645-3216 Cell

377-1858 Home

could not duplicate concern
 replace TPA, under bolt lock
 program cost 20.00, checkover
 + clean.

Quote

Serial
Number:**A6411404**

Model: 700



RE00197686

Invoice - NO BILL TO FOLLOW!