PERMITISPIAN BARBER - Kinzer PPS GAL RE 0010177

Remington Arms Co., Inc.

Product Service Legal Case #:5142

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

210841 11/18/2010 11/19/2010 11/19/2010

Customer Information

Street Type Business First Name Last Name City State Zip Age Contact

Incident Rudolph Buscher 100 South Vine Box 193 Chamois MO 65024 H 573-763-5627

Incident Information

Repair Medical Medical Claims Codes Est. Treatment Status

PΙ

PD Altered Adjustments or Cause:4006

Components Unknown Fired on bolt

S closing Concern: 1008 Fired on Bolt Closing

C

12/1/10 Per letter with rifle, firing pin on bolt did not come back out. When he put shell in and pushed bolt in shell went off.cm

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type CF/BA 700/270 WIN 25771 C6847403 BO 1/4/1994 Remington **Date Purchased** Where Purchased **Original Owner** Accessories

U

WAL-MART WAREHOUSE #3R

CONCRN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Cash Cash Release of Claims Release Date Settlement Reimbursement Date Date Settlement APV APV

Per Ilion, replace TPA, clean at 1/2 normal charges

> Repair/Replacement Repair/Replacement Cost Date

12/1/10 Per Ilion, will follow down. Trig assm dirty and set screws altered. Can offer to replace TPA, clean and test fire at 1/2 normal charges.cm 12/2/10 Spoke with Buscher by phone about the repair, he says he bought it new a WalMart and doesn't know how to adjust the trigger and it's never been to a gunsmith to be worked on either. I compromised and took the shipping and test charge off, he'll pay for the trigger and tax per our agreement.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code_	Comment	
	Examiner		B.TRAVIS	
	Exam Date		11/19/2010	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5142&Type=Case

12/2/2010

PrintDisplay	BER - Kinzer PPS GAL	RE 0010178	Page 2 of
	Product Type	1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	RF
Examination			A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description		22" 270 WIN
	Date Code		ВО
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		1
		Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	<u>'</u>
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
Doit	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
LAUacioi	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
] 1	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
i l'	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description	1 4130	STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	STANDING MITOU ON LET I
	<u></u>	Non-ISS	
Sear	Lift	Select	.014
	Notch	Slightly Worn; Functioning]
		Test Fired	False
Feeding Test	Tests	False	[
	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN DIRTY/STICK
ł	Pull	Select	2#
Trioger (Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

	(inzer-PPS GAL RE	al CHOOLED LESS 10018 Hebou	ts Table Maintenance	System Location		
						·
•		and the second second second	25 A Section 2. S			
	i. Augustini		•	A Carlon		•
•			-			
		W			¥u.	. :
			To The Second		Fit is a	
*****		ALL THE PROPERTY OF THE PARTY O			Salesien das	
3 de 18	frmREInquiry - Repair I	referrely				
	Repair Number: RE00210841 Se	rial: C6847403 Model 700 Center Fiv IN Produced: 01/04/1994 SKU: 25771	e Caliber, 270 , Repaiman.			
	Veniy Repar	IN Produced U1/U4/1994 5KU: 20//1	Status:	Repairing 11/19/2010 3:15:37 PM	**************************************	
	ADDRESS INFORMATION					
	Customer	Pacceived from	Return To	C Received from	2.802	
	Name: RUDOLPH V BUSCHER	232 <u>- 1710 2 150 5</u> 27 (2 14 14 2 5 10 1 10 5 10	RUDOLPH V BUSCHER	37.00 % 3-200468-0-30-2-3-2-2-2-2-2-		The Assert
	Address 1: 100 SOUTH VINE		100 SOUTH VINE	ji si		
	Address 2:	PO Box 193	3	PO Box 193		
	City: CHAMDIS		CHAMOIS			
	State: MO Zip Code: 65024	Country: US	M0 Zip Code 65024	Country US		
44.5.29		FIL (
	Contact / Condition Problems Estimate				i est	
				Current Status		114
	Date Code User ID		Detc2 Shipping Hold	Repairing		
	IFFE COUNTY New loperaft		Interlace Hold	11/19/2010 3:15:37 P) lopatafi	<u> </u>	
	11/19/2010 3 Maint Travisb	w RepairMaintenance S	latus: Repe	Repai Bench	jr,	
	TO FEE TO SE		Passed Inspec	Control of the contro		
	727 (22)		☐ Return as Reco	Current Location		
			☐ Has Been Appr	The state of the s		
	<u> </u>		Finlemal Repair ☐ Exclude TATC	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	Carrier Contract Cont					7
	RepairSearch		3 Sept. 18	i Refresh	Close	
				A STATE OF THE STA	e secretario de la companya della companya della companya de la companya della co	

	Mar. 1				(15.00 (
				na T		
				2013. 14 (15)		
			The second of th			

PECEIVE						
	NOV	2	C.≥	2010		
BY:						

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Serial Number: Model Number: Are you the original owner?: Date of Purchase: Buscher Name: Rudolph U Box 193 Address (no PO Boxes): 65024 hamois Fax: Phone (Daytime): 573 -E-mail Address: would like to receive future e-mail updates from Remington. Please describe your problem: **Ammunition Information:** WIN COX & Manufacturer: Remington Other (i.e. bullet weight/type, shot size, powder): Handload Information: Powder Used: Powder Weight: Case/Hull Used: Primer Used: Bullet Type/Shot Size: Reloader Used: Firearms Care (Cleaning and Lubrication): Brand of cleaning solution used: of rounds) of rounds) or Number of rounds)

[₿]C6847403



will hollow down, Trig. 435m.
Dilty + set sciews Altered. CAN
Offer to icp heetid, clean +
rest flice at 1/2 worms changes.







