ISPIAY
BARBER - Kinzer PPS GAL RE 0012766
Remington Arms Co., Inc.

Product Service Legal Case #:5138

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 11/18/2010 12/9/2010 12/8/2010 213186

Customer Information

Business First Name Last Name Street City State Zip Age Contact Type H 814-673-3847 Weisenfluh 1025 W. 3rd St Oil City PA 16301 Incident Kevin E kweisnfluh@comcast.net

Incident Information

Codes Medical Treatment Medical Status Claims Repair Est.

PI

PD Cause:4015 Improper Maintenance Unknown Concern:1007 Fired on Safe Release S Fired when safety was released

C

11/18/10 Per call from Weisenfluh, he has a 700 30-06 that was passed down to him from his uncle. Last year his father was shooting it and it fired when he released the safety. It has a bolt lock and he wants that removed.cm

Firearm Information

Model/Ga. SKU Mfg. Serial Bbl. DOM Type CF/BA 700/30-06 SPR n/a 363158 DR 1/1/1968 Remington Where Purchased Accessories **Original Owner Date Purchased**

N

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Release Date Reimbursement Settlement Date Settlement Date APV APV

Per Ilion, replace trigger, clean at BLSM program price

Repair/Replacement Repair/Replacement Date Cost 40.23 12/13/2010

11/18/10 Mailing ARS and box.cm 12/13/10 Per Ilion, Trigger assm very dirty and sticky causing parts to work sluggish. Replace TPA, clean and test fire under BLM program price for \$20 + shipping. Emailed Weisenfluh the estimate and inspect info.cm


Examination[Remington/CF/BA]

Examiner		
		B.TRAVIS
Exam Date		12/9/2010
Product Type		RF
Action Type		A
Assigned To		T.NAGLE
4015	Improper Maintenance	
Description		22" 30-06 SPR
Date Code		DR
Bore Plugged	False	
Bulged	False]
Fired	False]
/ / I	Action Type Assigned To 1015 Description Date Code Bore Plugged Bulged	Action Type Assigned To 1015 Improper Maintenance Description Date Code Bore Plugged False Sulged False

PrintDisplay Page 2 of 2

BARBER	Fired while Obstructed RE	0012767	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	SLUGGISH
Shroud		Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
 	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
<u> </u>	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	DIRTY STICKY TRIG NOT RETURNING
T-:	Pull	Select	4#
Trigger	Altered	False	·
,	Sub-Assembly	M/700 Bolt Lock	

*()	Joy.	pair, Number	Repair Inqu F00213186	ल्यों ताबुंदे <mark>रिक कि त</mark> ारक	363158 Model	700 Center Fire	Caliber: 3006		1 4 4 2 5 7 S N	The state of the s	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
		erify Repair		spirg				Status	New 12/8/201	07:43:33	AM.	きなる	
٠ <u>٠</u> .ف	1000	DDRESS INFORI	ATION:			14 15 25 47 75 E			为"有力"的"数"。 "第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十				
3	1	Cu	stomer			¶aceived from	n Return	To	ANTICOLOGICAL PROPERTY OF THE	C Rece	ived from		
ě	1	44.Exxxxx	VIN WEISENFL			instituti.	A CONTRACTOR OF THE PARTY OF TH	VEISENFLUH			-Western		
4			25 W. 3RD ST.	•	representation of the		1025 W	3RD ST.	anderlie are			是影響	
Š		Address 2	ps		PO Box			* 3 * ** mo. v 3 * * *	PO Box	1.583	_		
	松	City: OII		i i a a a a a a a a a a a a a a a a a a	— it edit kindler		OIL CIT		1.24.766.3	\$01a			À
	100	State. PA	Zip Code	16301	Country.	US	PA .	Zip Code 116301	Country	gjus	A CONTRACTOR		N.
	2 /4			ne ne se		FFL 1					2, 350	(2)	
		ontact 7 Condition	l'Problems I F	etimate : Histo	orv / Status I s	hinning / Billing				2 2 W	STATE OF	ALC MARK	
		A P. C. L. C.	7. 4. 4. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.							4.14.4			
		Date	Code (* e. *)	User ID	Z Desc1 🛬			Shipping Hold		Current Sta New			
),	12/8/2010 7:4:	New	lopatafl	Repair Adde	ed	1.5	Interface Hold		8/2010 _. 7:			
	ihic Hiv	12/8/2010 7:4	Expedite	lopatafi	From: Check	k In		⊏ Estimate Sent		lopata Repair B		8.438	
		12/8/2010 12:	EmailSent	ArmEmail	Repair Rece	eived		Parts Réceive	The second second second	Repair Loc		(4) (A)	
) (01) (1) (1) (1) (1)	12/8/2010 12:	EmailVerified	ArmEmail	Receipt		Livingiegoffich(1)	Return as Rec		(ILN	MATTER.		M.
¥.5	45°C	12/9/2010 2:3	Maint	Travisbw	Repair Main	tenance		Has Been Apr		urrent Loc			
1	100	i nuista	种态模器的聚	以来为政治	至西海河 云		MARTINE (III)	Internal Repai	and the second second second	ransfer Nu			3 .
-31		Ware (v.s.)	MAKE COM	机油油槽	NE TURN		Transfel Sa	Exclude TATC				阿瑟克斯	W.
1				在海州			14.00 mg						
, é. 3	7.4	Repair Seam							E. Carlotte and Control of the Contr	efresh :	All the age	ose,	
F		AND AND MARKET	त्राक्षित्र ^च ्य श्रीकत्वेश्वीत्री	and the second	を受けたい かい を使す care nonesco	and the grant of the second	en skaken er elle tre e	er in the second of the second	And Stations	"是我说 "		。 光明性的,充分	
L	27/2	technique forme		de adecativitada	en state in	2.2.267.2024.00	THE MALE	4.3. 2.4. 3.2. 5.1 18.4 19.	4.00 mg 12 mg 19 mg 12	A CONTRACTOR OF THE PARTY OF TH	8 000000000000000000000000000000000000	1980 P. 18	
					T-Way			e ()					
							and the same of th			-:-			
			.`	بَسَوَّهِ روي در	ALL THE								
						Commenter of							



5138

22"
Di29/68
44

November 18, 2010

Kevin Weisenfluh 1025 W. 3rd St. Oil City, PA 16301

Subject: #5138, Model 700

Dear Mr. Weisenfluh,

Enclosed is a UPS ground prepaid shipping label. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

enclosure

363158 Model: 700 RE00213186 T.A. Very DIRTY + STICKY CAUSING PARTS to WOILLE SCUQUES. PUPLACETPA CLARK TEST CIRC UNDER BLP CON \$ 20.00 + Ship

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington Ser - Kinzer PPS GAL RE 0012769

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: Model 700	Serial Number: 363158
Are you the original owner?: YES NO	
Name: Keuw Weisenfluh ->	Date of Purchase: 1.1986
Address (no PO Boxes): 1025 W 3rd	street
City: Oil CIty	State: PA Zip: 1-6301
Phone (Daytime): 814-673-3847	Fax:
E-mail Address:(if e-mail address is provided, notification	
sent) KWeisenfluh@comcast E-mail Address:	7Net
I would like to receive future e-mail updates from Rem	nington.
Please describe your problem and date of occurrence:	
	satety off and
Miss fired on taking ehamber new round	and missfired
Miss fired on taking ehamber new round	and missfired
Miss fired on taking ehamber new round	and missfired
Miss fired on taking ehamber new round	and missfired
Miss fired on taking ehamber new round	and missfired
	and missfired
500 characters left	and missfired
500	and missfired
500 characters left	Type: Silver tip
500 characters left Ammunition Information: Manufacturer: Remins Ton	
500 characters left Ammunition Information: Manufacturer: Remins Ton Other (i.e. bullet weight/type, shot size, powder): 180	Type: Silver tip
500 characters left Ammunition Information: Manufacturer: Remins Ton	Type: Silver tip
500 characters left Ammunition Information: Manufacturer: Remins Ton Other (i.e. bullet weight/type, shot size, powder): 180	Type: Silver tip
500 characters left Ammunition Information: Manufacturer: Remins ton Other (i.e. bullet weight/type, shot size, powder): 180 Handload Information:	Type: Silver tip

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: Hoppes
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Hoppies :
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your firearm was serviced by a Remington authorized
repairman/gunsmith?) UN KNOWN
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
●WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

