

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	out of box Inspection	TLW1203A		
TS	12-22-03	Detonate - Scope Crosshair Stress	Front 27 Rear 25		
BL	12-22-03	Headspace	Min +.002		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	Min +.002		
JS/BL	12-23-03	Depth Front take down same hole			
BL	12-23-03	Firing Pin Indent	.020-.002 Min .020 Avg. .0203		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0276		
JS	12-29-03	Sear lift	.0145		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.004			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min .004		
TS	1-14-04	200 Rd Basic Jack Function Test	ATEX116; Magazine was bent on front side	200	202
SW/BL	1/15/04	Headspace	Min +.004		
BL	1-16-04	Shoulder Function	1st x20 Rds. Shot clean	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection sheet - possible broken extractor		

Logform

ETI 9990

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-71

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS / BL

Round Level: 222

☒ Measure Headspace min + .004

☐ Sear Engagement: 1st. 2nd. 3rd.

Ave. spec- .020" to .025" **83**

☐ Trigger Pull: 1st. 2nd. 3rd.

Ave. spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☐ Inspect extractor & bolt face area. extractor looks ok wear and possible broken

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs have some wear

☐ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine box is protruding, receiver insert has a defect must be removed.

Couldnt do engagement or trigger Pull, Mike Keeney took K bolt head for evaluation.

TLW1303

Remington Confidential

ET19991