

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12-19-03	Out of box Inspection	TLW1302A		
JS	12-22-03	Detonate - Scope Crossbolt	Front Rear		
BL	12-22-03	Headspace	Min + .004		
BL	12-22-03	Proof	O.K.	1	1
BL	12-22-03	Headspace	Min + .004		
JS/BL	12-23-03	Depth Front Take down Screen hole			
BL	12-23-03	Firing Pin Indent	1021-0029 - .021 Avg. .0206		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0258		
JS	12-29-03	Sear lift	.0186		
SW/JS	1-13-04	Charge out Bolt Head			
SW/JS	1-13-04	Headspace	Min + .006		
SW/JS	1-13-04	Proof & Rd		1	2
SW/JS	1-13-04	Headspace after proof	Min + .006		
JS	1-14-04	200 Rd. Basic Function Test; Bolt failed to open on rds #181-200; Magazine was bent on front side		200	202
SW/JS	1-15-04	Headspace	Min + .007		
TC	1-16-04	Shoulder Function test X20 Rds.	Shot clean	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection Sheet - Broken extractor		

Logform

ET1992

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-12

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: TS/BLRound Level: 222☒ Measure Headspace mint, 0.005☒ Sear Engagement: 1st. 027 2nd. 0265 3rd. 0256Ave. 0263 spec. 020" to 025"☒ Trigger Pull: 1st. 4.123 2nd. 3.788 3rd. 3.699Ave. 3.870 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary. 4.606 5.215 5.157☒ Inspect extractor & bolt face area. extractor for broken☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: bolt stop excessive wear, locking lugs some wear☒ Inspect stock for any signs of cracking or other

failure. _____

☒ Other items ofnote: magazine box protruding - receiver insert has a defect must be
in the mold.

TLW1303

Remington Confidential

ET19993