

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

BARBER - 5.22.06r0003631

				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PA	12/14/03	Out of box Inspection	TLW1303A		
TS	12/22/03	De-Torque Scope	Cross Bolt screws Front 25 Rear 30		
BL		Headspace	Min + .005		
BL		Proof	OK	1	1
BL	12/22/03	Headspace	Min + .005		
TS/BL	12/22/03	Depth Front Take down screw hole			
BL	12/23/03	Firing Pin Indents	.019 .021 Aug. .0196		
JS	12-29-03	Seal/Trigger Engagement	Arg. .0294		
JS	12-29-03	Seal 1st	.0171		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min + .006		
SW/JS	1/13/04	Proof Ad		1	2
SW/JS	1/13/04	Headspace after proof	Min + .006		
B Lee	1/15/04	2000 JAC First test	Bolt hard to close from PRSC30WB / magazine hard to take from magazine with 30 TE	200	202
SW	1-15-04	Headspace	Min + .006		
BL	1-16-04	Shoulder fire	OK	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

Confidential - Submitter ID: 2019003637 Order

ET20010

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-21

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 200

- ☒ Measure Headspace min+.006
- ☒ Sear Engagement: 1st. 0294 2nd. 0273 3rd. 0282 Ave. 0283 spec. .020" to .025" **83**
- ☒ Trigger Pull: 1st. 4.323 2nd. 4.604 3rd. 4.608 Ave. 4.512 spec. 4 lb. to 5.5 lb.
- ☒ Check Take-Down Screws and Re-tighten if necessary.
- ☒ Inspect extractor & bolt face area. some wear on bolt face
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Lacking lugs somewhat, Bolt stop some wear
- ☒ Inspect stock for any signs of cracking or other failure.
- ☒ Other items of note: Magazine Box protruding

TLW1303

Remington Confidential

ET20011