

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/02	Out of box Inspection	TLW 1302A		
JS	12/22/03	Do-Torque Scope	Cross Bolt screws Front 40 Rear 30		
BL		Head space	Min T. 002		
BL		Proof	O.K.	1	1
BL	12/22/03	Head space	Min T. 002		
JS/BL	12/22/03	Depth Front Take down Scope hole			
BL	12/23/03	Firing Pin Indexis	.022-.022-.022-Avg. .022		
JS	12-29-03	Seal/Trigger Engagement	Avg. .0274		
JS	12-29-03	Seal lift	.0152		
SW/JS	1/13/04	change out bolt head			
SW/JS	1/13/04	Head space	Min t. .004		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min t. .004		
SW	1/15/04	200 Rd Basic Jack Function Test		200	202
SW	1-15-04	Head space	Min t. .004		
BL	1-16-04	Shoulder Fire	Bolt stop not working properly	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

BARBER - 5.22.06r0003641

Confidential - Suppression Order
 Williams v. Remington

ET20020

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-26

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222
☒ Measure Headspace min+.004
☒ Sear Engagement: 1st .0258 2nd .0265 3rd .0251
Ave. .0258 spec. .020" to .025" 83
☒ Trigger Pull: 1st 5.0752 2nd 5.039 3rd 5.045
Ave. 5.053 spec. 4 lb. to 5.5 lb.
☒ Check Take-Down Screws and Re-tighten if necessary.

☐ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt + stops excessive wear
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of
note: magazine Box protruding

TLW1303

Remington Confidential

ET20021