

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS RDS. FIRED	AT START-0 TOTAL RDS.
SW/PA	12-19-03	Out of Box Inspection	TLW1302A		
JS	12-22-03	Detonate Scope Crosshairs	Front 25 Rear 30		
BL	12-22-03	Headspace	Min +.005		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	Min +.005		
JS/BL	12-22-03	Depth Front Take down Scope hole			
BL	12-23-03	Firing Pin Indents	.020 - .022 - .030 Avg. .0286		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0298		
JS	12-29-03	Sear lift	.017		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.006			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.006		
JS	1-14-04	200 Rd. Basic Jack Function Test	Bolt head too close thru chest test; Bolt head to open on rds #181-200, Magazine was bent on front side	200	202
SW	1-15-04	Headspace Min +.006			
BL	1-16-04	Shoulder Function test X20 Pds. Short Chain		20	222
JS/BL	1-19-04	Chain & Inspect	See Inspection Sheet		

Logform

ET20134

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-14

TLW #: TLW1303

Date: 01 / 19 / 07Inspector: JS/BLRound Level: 222☒ Measure Headspace mint .006☒ Sear Engagement: 1st. .0282 2nd. .0269 3rd. .0275Ave. .0275 spec. .020" to .025"☒ Trigger Pull: 1st. 4.985 2nd. 4.496 3rd. 5.360Ave. 4.880 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Broken extractor☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Locking lugs some wear - Bolt stop some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine box is protruding - receiver insert has a defect must be on the mold.

TLW1303

Remington Confidential

ET20135