

CAL: 300 WIN MAG

PROJECT # 241314

BARBER - 5.22.06r0003761

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detonate - Scope	Front 20 Rear 15		
BL	12-22-03	Headspace	min + .006		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min + .006		
JS/BL	12-22-03	Depth Front Take down	Screw hole		
BL	12-23-03	Firing Pin Indent	.020 - .020 - .021 Avg. .0203		
JS	12-29-03	Gun/Trigger Engagement	Arg. .0274		
JS	12-29-03	Seq. lift	.0155		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min + .007			
SW/JS	1/13/04	Proof & Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min + .007		
JS	1-15-04	200 Rd Jack Function test	Bolt hard to close on Rds 61-80; 121-140	200	202
SW	1-15-04	Headspace Min + .007	Front & Rear Take down screws were loose		
BL	1-16-04	Shoulder Fine	Bolt hard to close	20	222
JS/BL	1-20-04	Inspect & Clean	See Inspection sheet - Broken extractor		

Logform

Confidential - Submitter ts.22.0616003766 Order

ET20140

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-17

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222☒ Measure Headspace min+.007☒ Sear Engagement: 1st. 0.282 2nd. 0.282 3rd. 0.274Ave. 0.279 spec. .020" to .025"☒ Trigger Pull: 1st. 4.193 2nd. 4.333 3rd. 4.283Ave. 4.270 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Extractor Bolt Face☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Locking lugs worn, bolt stop some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box protruding, receiver insert has defect must be to mtd.

TLW1303

Remington Confidential

ET20141