

CAL: 300 WIN MAG

PROJECT # 241314

[illegible]

Logform

BARBER - 5.22.06r0004067

ET21067

Confidential - Submitter - 502.P0610004067e Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-2

TLW #: TLW1303

Date: 3, 12, 104Inspector: J. SimsRound Level: 701

- ☒ Measure Headspace Min + .004
- ☒ Inspect Take Down Screws for loosening. Front take down 1/8 turn loosened, Center 1/4 turn loosened. 83
- ☒ Sear Engagement: 1st. .0295 2nd. .0293 3rd. .0294 Ave. .0294 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. 5.170 2nd. 5.090 3rd. 5.152 Ave. 5.039 spec- 4.5 lb. to 5.5 lb.
- ☐ Trigger Pull: 1st. 4.789 2nd. 5.045 3rd. 5.152 Ave. 5.039 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 5.170 2nd. 5.090 3rd. 5.152 Ave. 5.039
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, locking lugs, bolt stop all show some wear.
- ☒ Inspect stock for any signs of cracking or other failure: Cracked stock at the center take down screw hole
- ☐ Other items of note: _____
- _____
- _____
- _____

TLW1216

Remington Confidential

ET21068

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-2

TLW #: TLW1303

Date: 3 / 5 / 04Inspector: BLRound Level: 1401

- ☒ Measure Headspace mint. 004
- ☒ Inspect Take Down Screws for loosening. some movement during testing - note 83
- ☒ Sear Engagement: 1st. .0292 2nd. .0303 3rd. .0297 Ave. .0297 spec. .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 4.629 2nd. 4.489 3rd. 4.418 Ave. 4.512 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, Locking lugs, Bolt stop some wear
- ☒ Inspect stock for any signs of cracking or other failure: stock cracked at center take down screw hole
- ☒ Other items of note: Photo taken of Top screw - 65 in Lbs. to untorgue screw

TLW1216

Remington Confidential

ET21069