

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

[illegible]

Logform

BARBER - 5.22.06r0004070

Confidential - ~~BARBER - 502.F0610064070~~ Order

ET21070

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

75

35

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-3

TLW #: TLW1303

Date: 3 13 104Inspector: BLRound Level: 701

- ☒ Measure Headspace mint .003
- ☒ Inspect Take Down Screws for loosening. Top screw 1/8 Turn - Center 1/4 turn 83
- ☒ Sear Engagement: 1st. .0378 2nd. .0378 3rd. .0379 Ave. .03783 spec- .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. .0289 2nd. .0289 3rd. .0292 Ave. .0290
- ☒ Trigger Pull: 1st. 6.407 2nd. 6.415 3rd. 6.415 Ave. 6.452 spec- 4.5 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st. 4.855 2nd. 5.078 3rd. 4.764 Ave. 4.882
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, Locking Lugs, Bolt stop show some wear
- ☒ Inspect stock for any signs of cracking or other failure: Stock cracked at the Center Take down screw hole

☐ Other items of

note:

TLW1216

Remington Confidential

ET21071

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-3

TLW #: TLW1303

Date: 3 / 5 / 04Inspector: BLRound Level: 1201

- ☒ Measure Headspace min^t.003
- ☒ Inspect Take Down Screws for loosening. Some movement during test - Retorque 83
- ☒ Sear Engagement: 1st. .0290 2nd. .0286 3rd. .0296 Ave. .02906 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 4.607 2nd. 4.464 3rd. 4.519 Ave. 4.530 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, bolt stop show signs of wear
- ☒ Inspect stock for any signs of cracking or other failure: stock cracked at center screw hole
- ☒ Other items of note: Photo taken of Top screw - 50 in Lb to untorque screw

TLW1216

Remington Confidential

ET21072