

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-11

TLW #: TLW1530

Date: 9 / 8 / 04

Inspector: SW

Round Level: 2240

☒ Measure Headspace Min +.002

☒ Sear Engagement: 1st. .0353 2nd. .0351 3rd. .0352 Ave. .0352 spec. .020" to .025" 83

☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____

☒ Trigger Pull: 1st. 4.764 2nd. 4.628 3rd. 4.663 Ave. 4.685 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____

☐ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs normal wear, bolt stop little wear.

☒ Inspect stock for any signs of cracking or other

failure. Cracked (see Todd Cook) Stocks show a crack / 45° anterior
from the recoil lug. Crack runs .200"± and is nearly completely closed.
These appear better than the old material when tested w/ 30'00. PMS JMC

☐ Other items of

note: _____

TLW1216

Remington Confidential