

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-15

TLW #: TLW1530

Date: 9 / 8 / 04Inspector: SNRound Level: 2221
☒ Measure Headspace Min +.006
☒ Sear Engagement: 1st. .0350 2nd. .0356 3rd. .0353 Ave. .03530 spec. .020" to .025"
☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____

☒ Trigger Pull: 1st. 4.539 2nd. 4.561 3rd. 4.582 Ave. 4.561 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____

☐ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Locking lugs show wear
☒ Inspect stock for any signs of cracking or other failure. Cracked (See Todd Cook) 45° anterior crack is only on shooter's right ~0.225"± and nearly closed. This is better than the old material on 30-06. PASS 7/06
☐ Other items of

 note: _____

TLW1216

Remington Confidential

ET23050