

11. Problems

11. M/121 Action Bar Oper. 46-2. Position of slot length-wise from locating holes appears to have too wide a taper to hold in gage limits.

a. It was decided to request temporary Process Deviation until job is investigated.

A. Prokop to follow.

111. Remarks

The current Weekly Quality Index was discussed and necessary corrective action taken.

W. Wood
For the Committee