

5-3-63
part 3.

1. Seams (PM) seem smooth. Top corner rounded off.

Production Seams sharp to corner. Still have grind grooves across seam cam surface.