


after tests on 11-15-65

Diff 139413

5200 can surface that contacts Firing? in head
can surface. Shiny spots showing which means
some wear but not excessive. corner is similar
place.



in contact on flat surface. very
light.

5200 surface that contacts connector surface. w/ oil on surface it looks like a deposit of rust. when oil is removed it looks clean & shiny.

connector surface with oil on it looks as though it has a varnish or rust film. when oil is removed the surface was shiny & shows the surface that it is in contact with the 5200.




Diff 139555

5200 can surface same as above

5200 surface that contacts connector same as above.

connector surface same as above except that when oil is removed there are still some spots that will not = varnish or rust.



prints still
me too