

100 ROUND BASIC JACK FUNCTION TEST

- 14 GUNS STARTED THE TEST
- 1 GUN STOPPED @ 88 RDS. BECAUSE OF MAG FOLLOWER BINDING
- 1 GUN STOPPED @ 62 RDS. BECAUSE MAG BOX BOTTOM CAME OFF
- 2 GUNS STARTED HAVING STEM LOW PROBLEMS CAUSED BY FOLLOWER BINDING DURING THE TEST AND WERE STOPPED SHORTLY INTO THE EXTENDED 400 RD. TEST
- 1 GUN'S GRIP CAP CAME OFF DURING THE TEST

Of the 9 guns that completed the test without issues there were 2 feeding malfunctions.

*11 complete thru 100 rd.*

400 ROUND EXTENDED FUNCTION TEST

- 9 GUNS STARTED TEST
- 2 GUNS WERE STOPPED DUE TO THE MAG FOLLOWER BINDING AND CAUSING STEM LOWS (NOTED ABOVE)
- 2 GUNS HAD THE BOX BOTTOM COME OF DURING TEST
- 5 GUNS LOST GRIP CAPS DURING TESTING

Of the 7 guns that completed the test there was no feeding malfunctions.

ET28024