

MI 700 DVL. 1155 STON
EXTREME CONDITIONS

10-24-79

C. J. Sweet

	1	2	3	4	5	6
	Started-10-24-79	Stock #1	Stock #2	Stock #3	Stock #4	Stock #5
		Cold Test - Pressed	Freezer 0°	Heat Test - Pressed	OVEN 240°	Stocks on Roof Pressed
1						
2	After 17 hrs.	Reinforcing web cracked	No cracks	8" crack	No cracks	Cracks
3	10-25-79	1/2 way thru		INSIDE OF REIN. ROD		Cracks
4						Rail over Night
5						3 1/2" - 4" x 1"
6	After 20 hrs	No Change	No Change	No Change	No Change	Water has
7	10-25-79					been absorbed
8	Took Stocks					in checking
9	#1 & 2 and Put them in the oven 240°					around butt
10	#3 & 4 were put in the freezer at 0°					plate. Cracks
11						Present at rear
12				Reinforcing web slight crack	Reinforcing web cracked	web & behind
13	After 20 hrs	Reinforcing web 3/4" crack	No cracks	crack due to cold test	All the way through.	Rail Lug
14	10-26-79		Usual Cracks		Whole area	
15					Area behind	
16					Rail Lug	
17					Cracked	
18					through.	
19					Cracks	
20					occurred in	
21					Freezer	
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						

NATIONAL | 111 30 102 1 1053 2700

10-24-57

CH. 10

BARBER - PRESALE R 0107767 R2508755