XC: \ J. P. Linde

REMINGTON ARMS COMPANY, INC.

ter-departmental correspondence

Remington

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"_

Jile m/700

May 6, 1981

TO: J. J. BURNS

FROM: W. A. WARREN, JR.

WAREHOUSE AUDIT - M/700 CAL*S 7x57 AND 7MM-08 - VISUAL

Twenty guns per caliber were withdrawn. These have been visual inspected to normal phase 1 standards, by Finish Gun Auditer R. F. Leskovar. Deficiencies are tabulated without assigning a demerit value.

The guns were warehoused between April 23rd and 28th, 1981. All were examined April 30, 1981.

No defects were found on 22 of the 40 guns. Results are tabulated separately by caliber and for the two groups combined.

COMBINED RESULTS OF 40 GUNS

Listed in descending order

Excess checkering sealer Poor color white spacers Shallow checkering cuts Checkering over-runs Chipped wood	7 6 3 3

Metal. Other wood Total

The five most prevalent items are wood. They account for over one half of total.



- 2 -

WAREHOUSE AUDIT - Contd.

M/700, Cal. 7MM-08

Date packed: April 28, 1981

NO DEFECTS ON 9 GUNS

VISUAL DEFECTS

METAL

Listed in descending order

<u>wood</u>

110 00.			
Checkering: Excess sealer Overruns	6 3	Color: Poor on bolt handle	2
Finishing: Poor color, spacers Residue, bolt handle	·6 slot l		
Damage: Chipped	2		
TOTALS	18		2
	DIMENS	CIONAL	
		Sear Safety Cam Unground Fails screwdriver test (.006 lift "On Safe")	5
TOTALS	0 OTH	SR .	5
		Incorrect magazine follower	2
TOTALS	0		2
TOTAL WOOD	18	TOTAL METAL	9
Total items found on 7MM-0	8's: 27		

WAREHOUSE AUDIT - Contd.

M/700, Cal. 7x57 Mauser

Date Packed: April 23, 24, 25, 1981

NO DEFECTS ON 13 GUNS

VISUAL DEFECTS

Listed in descending order

WOOD		<u>METAL</u>	
Finishing: Runs Excess stain Open grain Poor repair	2 1 1	Turn marks on Bolt Plug	1
Checkering: Shallow cuts Excess sealer	3 1		
Damage: Marred Chipped	2 1		
TOTALS	12		1
	DIMENSIONAL]	
Safety clearance Cut not uniform	1		
TOTALS	1		0
TOTAL WOOD	13	TOTAL METAL	1
Total items found on 7x57's:	14		

WAW/cac