

REMINGTON MODEL 710 Trial and Pilot SERIES C PRELIMINARY MEASUREMENTS

FIRECONTROL INSPECTION TLW0300AU			FIRING PIN ASSEMBLY INSPECTION		FIRING PIN HEAD TO SEA		LEASE FUNCTION TEST	ISS FUNCTION TEST
TRIGGER RETURN	GAP	SEAR MOVEMENT	CHECK FOR	TIGHTNESS	measurement method	TLW03000, GUNS	C-11 TO C-20	GUNS C-11 TO C-20
out of stock @ 2	20x	in stock by feel	TIP	OK OK	produces a dimension range	STOP FUNCTION	RELEASE DETENT	
OK	NONE	FREE	ok	OK 🎉	.056069			}
OK	NONE	FREE	OK	OK """	.061072			,
OK	NONE	FREE	ok	LOOSE	.062073			
OK	NONE	FREE	OK	OK,	.070081	1		į
OK	NONE	FREE	OK	LOOSE	.066077			}
OK	NONE	FREE	ok	OK CK	િં <u>.</u> .064075			
OK	NONE	FRÉE	ОК	ок 🛞	్ట్ 064075	Ì		ł
OK	NONE	FREE	ok	OK 🖏	्र ^{ूर} .064075			
OK	NONE	FREE	OK	LOOSE	.068079			
OK	NONE	FREE	OK	OK	966,077			
OK	NONE	FREE	OK	LOOSE	.067-078	OK	GOOD	PASS
OK	NONE	FREE	ОК	OK	070-081	ок	GOOD	PASS
OK	NONE	FREE	ok	OK		OK	GOOD	PASS
ОК	NONE	FREE	ок	OK	064075	ок	GOOD	PASS
OK	NONE	FREE	OK	OK	.066-97%	ок	GOOD	PASS
OK	NONE	FREE	OK	LOOSE	964-075	ок	POOR, LOOSE	PASS
OK	NONE	FREE	OK	OK	.069-:080	ок	GOOD	PASS
OK	NONE	FREE	OK	LOOSE	.065 076 പ്രാതി	ок	POOR, LOOSE	PASS
OK	NONE	FREE	oĸ	OK	966_077	ОК	GOOD	PASS
OK	NONE	FREE	ок	OK	266 -077	ОК	GOOD	PASS
OK	NONE	FREE	OK	LOOSE	.065076	1		ł
OK	NONE	FREE	ОК	OK	.062073	<u>.</u>		
OK	NONE	FREE	OK	OK	.068 079	%		
OK	NONE	FREE	ок	LOOSE	.070081	S.32		
OK	NONE	FREE	OK	OK	رۇپىي 062073.	11265. P		
OK	NONE	FREE	oĸ	LOOSE	.064075	1		
OK	NONE	FREE	OK	LOOSE	.062073	1		
OK	NONE	FREE	ок	LOOSE	.069080 శక్రమన్న	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		
OK	NONE	FREE	oĸ	OK	.064075	1.0 Pm		
OK	NONE	FREE	OK	LOOSE	.067078	18		

12 OF 30

ET34166